NOTE: ALL DRAINAGE LEVELS SHOWN IN IMPERIAL (FEET)

BM 76.84m

Corridor
Toilet
Quadrangle
Housing Filing
Store
Store
New Office
cover level 250.5
invert level 246.5
Interview Room 3
Payment Room
Homeless And Allocations Recption
Reception
Quadrangle
Lift
Shower
Female toilet
invert level 247.177
Corridor
Store
Toilet
Entrance
Corridor
150 dia foul drain
surface water drain
150 dia foul drain
surface water drain
150 dia foul drain
surface water drain
150 dia foul drain
150 dia foul drain
150 dia foul drain
150 dia foul drain
150 dia foul drain
invert level 247.52
150 dia foul drain
invert level 247.17
cover level 251.00
invert level 247.7
level 251.44
level 242.4
level 244.85
level 244.00
invert level 241.03
invert level 240.19
cover level 240.2
invert level 238.21
225 dia foul drain
225 dia foul drain
225 dia foul drain

NOTE: ALL DRAINAGE LEVELS SHOWN IN IMPERIAL (FEET)

Existing Ground Floor

MEDWAY
22 APR 2009
RECEIVED

ORIGINAL

Rev:	
Date: Nov 08	Scale @A1: 1:100

Title:
Charing Health Care Ltd
Gillingham Municipal Offices
Existing Ground Floor Plan

Drawing No:
1039 / 08 / 101

crofton design services limited
3 Rice Parade, Fairway, Petts Wood Orpington, Kent. BR5 1EQ
t. 01689 836855 f. 01689 836855
e. design@croftondesign.co.uk
www.croftondesign.co.uk

© CDS Ltd. 2008

MC2009/0536